



J2 TECHNICAL ARTICLE

Number 19

From Octagon Heaven

April 21, 1981

Resource: M.G. Car Company
Issued April, 1933

SERVICE INFORMATION SHEET NO. 8J -- CLUTCH INSPECTION COVERS

SERVICE INFORMATION SHEET NO. 8J

April 1933

CLUTCH INSPECTION COVERS

It has been pointed out that there have been instances of the Clutch Inspection Covers fitted to our J-type Power Units being fitted upside down.

This brings the air vent of the Clutch Chamber to the nearside instead of the offside as it should be.

This results in air being pumped out of the Clutch Chamber and draws oil out of the Rear main bearing and the gearbox onto the Clutch.

With this point in view, a Drawing has been prepared to show the Inspection Plate as an Aluminium Casting with an MG Monogram and a locating pin.

To fit this cover it is necessary to drill a hole in the Clutch Housing.

These improved covers are being fitted to Cars returned to the Works for overhaul. In the event of any of these covers being required the Part Number is 2332.

MG Car Company Ltd.

(Change-over must have been about Chassis No. J2/3000 by the look of it. Ed.)