

## J2 TECHNICAL ARTICLE

Number 59

From Octagon Heaven

December 17, 1981

Resource: M.G. Car Company Ltd.  
Issued June 1933


### INFORMATION SHEET NO. 5 -- GEAR LEVER RATTLE

Complaints of rattle in the gear change remote controls have been made from time to time, and up till recent no very satisfactory cure has existed.

It has been found that a spring fitted as shown in the drawing (Service Blue Print No. 146) prevents rattle most effectively.

These springs are very easily fitted and any complaints can therefore be quickly dealt with.

The Part Number of the spring in question is 2747, and this number, together with the chassis Number of the car concerned, must be quoted when ordering for service.



spring must sit on actuating lever.