




J2 TECHNICAL ARTICLE

Number 104


April 13, 1982

From Octagon Heaven

Resource: Pre-War M.G. Parts Centre

BOTTOM FIREWALL (BULK HEAD) RUBBER FUME SEAL

Question: The bottom firewall rubber fume seal looks like the sketch below. How does it fit over the bulk head? Does it fit only over the front "skin" or does it fit over the whole thing?




Approx 38" LONG

Answer: "The sketch on the lower left is the way we do it but the factory stretched the rubber over both plywood and sheet metal on the lower side. I am now finding with a little lubrication, such as washing liquid, the rubber will go over the complete firewall at the top."

Barry Walker

"The way we do it"

"The factory way"



factory could (Editorial note: If the factory could do it the so can I!) but I don't know if I