

J2 TECHNICAL ARTICLE

Number 205


July 5, 1984

From Octagon Heaven

Resource MMM Infoletter
G. Lilley


LIGHTENING THE FLYWHEEL (IF THAT IS WHAT YOU WISH TO DO)

This is for whatever value it might be worth!



Machine as follows to reduce a moderate amount of weight when required.

3rd. Operation-Remove 14m.m. groove all round.
to accomodate new bolt-heads. (bolts replaci studs)



1st. Operation
Remove 15m.m. wide
groove 10m.m. deep.
from outside dia.

2nd. Operation- Drill
5/16" right through.

If starter ring is worn, turn off and rebate to
dimensions given by manufacturer of new ring.

NOT TO SCALE

G. LILLEY